HABS No. DE-218

Brick Store
Road 488, .7 miles east of
Road 489
Smyrna Vicinity
New Castle County
Delaware

HABS DEL, 2-SMYR.N, 2-

PHOTOGRAPHS
REDUCED COPIES OF MEASURED DRAWINGS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC RECION NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Form 10-920 (June 1983)

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS DEL, 2 SMYR.Y, 2-

## ARCHITECTURAL DATA FORM

STATE	COUNTY	TOWN OR VICINITY	
Delaware	New Castle County	Blackbird Hundred	
HISTORIC NAME OF STRUCTURE (INCL.	UDE SOURCE FOR NAME)		HABS NO.
Brick Store			DE-218
SECONDARY OR COMMON NAMES OF S	TRUCTURE		
Brick Store Farm			
COMPLETE ADDRESS (DESCRIBE LOCA)			
	inus of county route 488, .7 $_{ m m}$ 89; Located on the north bank (		
DATE OF CONSTRUCTION (INCLUDE SC			
1767 (dated with glazed			
SIGNIFICANCE (ARCHITECTURAL ANO	HISTORICAL, INCLUDE ORIGINAL USE	OF STRUCTURE	<del>!</del> )
	known colonial period agricult ty. It was built as a creek st		
STYLE (IF APPROPRIATE)	Ting before 1010.		
MATERIAL OF CONSTRUCTION (INCLUI used on land (northwest)	DE STRUCTURAL SYSTEMS) Brick: g elevation; common bond on gab	glazed heade ble ends and	r Flemish bond creek side elevatio
SHAPE AND DIMENSIONS OF STRUCTU	RE (SKETCHED FLOOR PLANS ON SEPAI	RATE PAGES AR	RE ACCEPTABLE)
Period I: 3 roughly equa	1 size storage and processing	bays. Perio	d II: middle
EXTERIOR FEATURES OF NOTE	y entry and unheated inner roo	m; chimney	piles added.
Glazed header date - 176	7. Scaffolding holes in masonr d side openings (later enlarge		for original
Common rafter roof with three light common purli	IBE FLOOR PLANS, IF NOT SKETCHED) double tier of half dovetail 1 ns per each roof elevation. Per overmantels and chimney close	riod II pan	
MAJOR ALTERATIONS AND ADDITIONS	WITH DATES		
to conversion made in or mid 19th-century insuran	y 1810. Unchanged since early phans court property valuation ce policy.		
PRESENT CONDITION AND USE	miamatada kuillina mmaamaadaa	ta muimana	Ohaha
rough storage; roof hete	riorated; building progressing	to rumous	state.
OTHER INFORMATION AS APPROPRIAT	E		
COLUDER OF INFORMATION (INC. LICIA	IC LISTING ON NATIONAL BEGISTED OF	TATE DECICES	20 C70 I
National Register of His	<i>IG LISTING ON NATIONAL REGISTER, S</i> toric Places	IAI E NEGISTEF	10, E / U.)
	Store: Architectural Study (un	published r	eport, 1979)
COMPILER, AFFILIATION		Ţ,	DATE
ł	r for Historic Architecture		3-5-85